## **LMA District Cover Sheet**

### **Spring 2010 Levee Inspection Results**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)							
* Overall LMA Rating (Fall Only)											
	** Non-receipt of Su	mmer or Winter Inspe	ction Reports may effec	ct overall annual rating.							
* SPRING INSPECTIONS: Overall maintenance deficiencies are rated	ratings are not determ d using the same criter			ual maintenance							
FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.											
Comments											

### **Unit Cover Sheet**

# **Spring 2010 Levee Inspection Results**

	Waten	way		Bank	Unit Miles							
	Unit No. 01 Ca	iche Slough		Left	7.40							
	Spring (March - May)	Summer (June - August)	(September - November) Fall		Winter ber - February)							
Unit Maintenance Rating (Fall Only)												
Date of Inspection	5/15/2010 - 5/15/2010											
DWR Inspector	Herman Phillips											
Accompanied By												
project components conditions other that	rinter (or summer) inspection p identified in the attached Leve n the results of our normal mai d in the enclosed report.	e Inspection Report by	Mile. We have found no chang	ges in flo								
<ul> <li>During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.</li> <li>(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).</li> </ul>												
Comments												
information must also be s	3	eet should be signed an	d dated by the LMA Represen th 31 (Winter Inspection). Plea spection Reports , Room LL-30	itative an	nd returned to							
x												
Signature of LMA Repres	entative		Date									

### Levee Inspection Report By Mile - Spring 2010

# **Reclamation District No. 2104 Peters Pocket Tract**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough	Left	7.40	05/15/2010 05/15/2010	Herman Phillips

LMR	Levee	Mile	Category	gory Item Location		Rati	Action/Comment	GPS Latitud	de/Longitude	Issue No.
No.	Start	End	Category	Item	tion	ng	Action/Comment	Start	End	Photo
1			Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.299220 ° -121.749828 °	0	7
2	0.01	2.60	Earthen Levee	Vegetation	CR	M	Control annual grass and weeds on the levee slopes and easements.	38.294084 ° -121.740246 °	38.291579 ° -121.726160 °	4
3	0.19	0.22	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.305912 ° -121.757515 °	38.305583 ° -121.757215 °	2
4	0.20	0.22	Earthen Levee	Vegetation	WS	М	Remove the wild growth other than native grasses from the levee slopes.		38.305547 ° -121.757178 °	17
5	0.27	0.27	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.		38.305022 ° -121.756692 °	1
6	0.30	0.30	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.304657 ° -121.756570 °	38.304657 ° -121.756570 °	18
7	0.31	0.31	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.304662 ° -121.756520 °	38.304662 ° -121.756520 °	3
8	0.40	0.40	Earthen Levee	Vegetation	WS	М	Control annual grass and weeds on the levee slopes and easements.	38.303417 ° -121.756473 °	38.303417 ° -121.756473 °	19
9	0.42	0.49	Earthen Levee	Vegetation	LS	М	Remove the wild growth other than native grasses from the levee slopes.		38.302260 ° -121.755987 °	5
10	0.42	0.67	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.303058 ° -121.756542 °	38.300238 ° -121.754347 °	6
11	0.63	0.94	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.300652 ° -121.754665 °	38.299348 ° -121.749995 °	20
12	1.36	1.37	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees over roadway to at least 12 feet above ground level.	38.296237 ° -121.744327 °	38.296158 ° -121.744262 °	9
13	1.37	1.38	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.296168 ° -121.744355 °	38.296110 ° -121.744300 °	13
14	1.43	1.49	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.295732 ° -121.743288 °	38.295697 ° -121.742408 °	10
15	1.43	1.60	Earthen Levee	Vegetation	ws	U	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: The growth need to be removed from levee section this unit has not had any maintenance since the last inspection.		38.294835° -121.741192°	11 Y
16	1.52	3.43	Earthen Levee	Vegetation	CR	М	Control annual grass and weeds on the levee slopes and easements.		38.301323 ° -121.730385 °	21

\* Location LS : Land Side

WS : Water Side CR : Crown

A : Acceptable M : Minimally Acceptable U : Unacceptable

PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected

C : Corrected W : Watch/Monitor

# Levee Inspection Report By Mile - Spring 2010

# **Reclamation District No. 2104 Peters Pocket Tract**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough	Left	7.40	05/15/2010 05/15/2010	Herman Phillips

LMR	Levee	Mile			Rat	Anting (Organism)	GPS Latitud	de/Longitude	Issue No.	
No.	Start	End	Category	Item	ation	*ing	Action/Comment	Start	End	Photo
17	1.55	1.60	Earthen Levee	Trim / Thin Trees	WS	U	Trim trees to at least five feet above ground level. Inspector Comments: The District has done no maintenacne here since last inspection.	38.295462 ° -121.741443 °	38.294912 ° -121.741178 °	12
18	1.57	1.60	Earthen Levee	Vegetation	WS	М	Remove the wild growth other than native grasses from the levee slopes.	38.295263 ° -121.741415 °	38.294915 ° -121.741277 °	22
19	1.69	2.60	Earthen Levee	Vegetation	CR	U	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: This unit has not improved since the last inspection, noithing has been done.	38.294125 ° -121.740428 °	38.294290 ° -121.726933 °	15
20	2.08	2.09	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	38.292027 ° -121.734575 °	38.291947 ° -121.734453 °	16
21	3.75	4.38	Earthen Levee	Vegetation	CR	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: This levee section is in need of maintenance to control the wild growth from water side and land side of levee section. This is typical all the way to the end of unit 1.	38.304825° -121.731143°	38.311318° -121.736635°	23
22	4.06	4.38	Earthen Levee	Vegetation	WS	М	Control annual grass and weeds on the levee slopes and easements.	38.307758 ° -121.734322 °	38.311318 ° -121.736635 °	24
23	4.58	4.65	Earthen Levee	Vegetation	ws	M	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: This levee is overgrown and is in need of maintenance. There are weeds taller than 5-feet tall on the levee section.	38.313130 ° -121.739023 °	38.313872 ° -121.739830 °	25
24	5.51	6.75	Earthen Levee	Crown Surface / Depressions / Rutting	CR	М	Regrade the crown roadway for proper drainage.	38.322340 ° -121.748377 °	38.316815 ° -121.758227 °	26

LS : Land Side WS : Water Side CR : Crown \*\* Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected W : Watch/Monitor

### Levee Inspection Report By Mile - Spring 2010

## **Reclamation District No. 2104 Peters Pocket Tract**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Cache Slough	Left	7.40	05/15/2010 05/15/2010	Herman Phillips

Levee Mile Report Line	15
Start Levee Mile	1.43
End Levee Mile	1.60
Location	Water Side
Category	Earthen Levee
Item	Vegetation
The same at a selection to a second	

This photo shown here was listed with a U rating. The water side is completely over grown from shoulder to beyond waterside toe. The crown has weeds 2-feet tall.

phillips\_s\_20100517\_040.jpg

Levee Mile Report Line	15
Start Levee Mile	1.43
End Levee Mile	1.60
Location	Water Side
Category	Earthen Levee
Item	Vegetation

standing on L/M 1.60 Looking downstream to 1.98 land ward levee over grown. This levee has not had any maintenance since last inspection.

phillips\_s\_20100517\_041.jpg





Friday, July 09, 2010 14:31

### **Unit Cover Sheet**

# **Spring 2010 Levee Inspection Results**

	Waten	way		Bank	Unit Miles							
	Unit No. 02 Ha	aas Slough		Right	4.80							
	Spring (March - May)	Summer (June - August)	(September - November) Fall		Winter ber - February)							
Unit Maintenance Rating (Fall Only)												
Date of Inspection	5/15/2010 - 5/15/2010											
DWR Inspector	ector Herman Phillips											
Accompanied By												
project components conditions other that	vinter (or summer) inspection p identified in the attached Leve n the results of our normal mai d in the enclosed report.	e Inspection Report by	Mile. We have found no chang	ges in flo								
deficiencies identified in the enclosed report.  During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.  (In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).												
Comments												
information must also be s	3	eet should be signed an	d dated by the LMA Representh 31 (Winter Inspection). Pleaspection Reports, Room LL-30	itative an	d returned to							
x												
Signature of LMA Repres	entative		Date									

## Levee Inspection Report By Mile - Spring 2010

# **Reclamation District No. 2104 Peters Pocket Tract**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Haas Slough	Right	4.80	05/15/2010 05/15/2010	Herman Phillips

LMR	Levee Mile		Catagony	Item	Item		Action/Comment	GPS Latitud	Issue No.	
No.	Start	End	Category	цеш	tion	ing	Action/Comment	Start	End	Photo
1	2.60	4.80	Earthen Levee	Vegetation	LS	М	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: The levee crown road way from 2.60 to 4.80 the district has mowed the crown. The live stock has grased on the slopes.	38.291579° -121.726160°	38.309465° -121.758088°	1 Y
2	2.74	2.80	Earthen Levee	Vegetation	LS	М	Remove the wild growth other than native grasses from the levee slopes.	38.293450 ° -121.726645 °	38.294283 ° -121.726932 °	16
3	2.79	2.80	Earthen Levee	Erosion / Bank Caving	LS	М	Note and monitor erosion site.	38.323780 ° -121.752410 °	38.323730 ° -121.752430 °	19

LS : Land Side WS : Water Side CR : Crown

Friday, July 09, 2010 14:31

\*\* Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected

C : Corrected W : Watch/Monitor

## Levee Inspection Report By Mile - Spring 2010

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Haas Slough	Right	4.80	05/15/2010 05/15/2010	Herman Phillips

Levee Mile Report Line	1		
Start Levee Mile	2.60		
End Levee Mile	4.80		
Location			
Category	Earthen Levee		
Item	Vegetation		
District keep the crown mowed and the livestock in area fird on the slopws. Standing on levee mile 4.80 looking back upstream.			
phillips_s_20100517_042.jpg			

